



Update instructions for SDM3055 P11R1 Version


The reason: Solve the problem that stays at the logo interface when booting




Tools: U-disk

Steps:



Step1.


First you must update the transition file *transition.ADS*





Press the left arrow key to choose the file.





reboot




Step2.

After the transition updated, you can update the normal version

sdm305 (V100R001B01D01P11R1).ADS

Press the left arrow key to choose the file.





Reboot twice